Annual General Meeting Independent Environmental Monitoring Agency

The Board

KITIKMEOT INUIT ASSOCIATION
APPOINTED JAYKO PALONGAYAK

NO STAFF CHANGES, BUT
COMMUNICATIONS SPECIALIST
ON MATERNITY LEAVE



Ron Allen, Bill Slater, Marc Casas,, Kim Poole, Emery Paquin, Jesse Jasper, Tim Byers and Jamie Mistry



Point Lake Pi


Activities & Exploration

- New owner of mine: Burgundy Diamond Mines Ltd
- Open pit mining of ore from Point Lake expected to begin in 2025
- Exploration drilling on Glowworm & Lac de Gras claim blocks ended in October 2023; the Land Use Permits terminated more than 1 year ahead of their expiry dates
- Sable pit & Misery underground were the sources of kimberlite ore for 2023 processing



Wildlife Effects

- Higher numbers of caribou sightings & lower numbers of wolverine sightings; number of incidents involving grizzly bears increasing.
- Traffic data on major haul roads collected using remote cameras for most of 2023.
- Preliminary results of Burgundy's caribou collar movement study were released, a welcome first step in evaluating the effectiveness of the Caribou Road Management Plan.
- The process to update the Wildlife Management and Monitoring Plan appears to have stalled.



Aquatic effects

- Aquatic Effects Monitoring Program monitors and reports changes to the lakes and streams downstream of the mine.
- Changes observed in 2023-24 include:
 - CHROMIUM under ice in Cujo Lake spiked to levels significantly greater than any previous years.
 - POTASSIUM & CHLORIDE in Leslie Lake continue to exceed Aquatic Response action levels.
 - SELENIUM in Leslie Lake sediments exceeded levels of concern for 2nd consecutive monitoring year.

Incinerato

Air quality

• Air quality generally good; but **dustfall** is significantly higher within 90 m of haul roads.

Changes in snow chemistry & lichen tissue up to
 10 km from mine due to mine activity in winter.

Waste rock Management

- 18 million tonnes of rock from Sable and Misery underground deposited on 3 waste rock piles & the Coarse Kimberlite Rejects pile in 2023.
- Point Lake rock pile design approved by WLWB, allowing deposit of Point Lake rock and ore stockpile to begin.
- New ecologically-based approach to rock pile seepage approved by WLWB.

Wastewater & PK Management

- Total of 790,000 m³ was discharged in 2023-24, all of discharge was from King Pond Settling Facility (KPSF).
- Burgundy discharged 319,000 m³ more water than was authorized in their Water Licence. This water was mainly from dewatering Point Lake.
- Renewed Water Licence:
 - authorized pumping fresh water from Upper Exeter Lake → LLCF if needed in case short on water for the Process Plant.
 - improved managing of LLCF dams: will help develop a management system that reflects best-practice for mine dam management in Canada.

Closure and Reclamation

- Latest updated ICRP not approved: April 2026 deadline for new version.
- Pigeon closure designs for pit & waste rock pile.
- Security:
 - Total increased by \$20.7 M
 - Intend to convert from security bond to cash
 - GNWT reviewing its policies on form of security, to address concerns about surety bonds

TK & Community Engagement

- There was little engagement with Elders and communities regarding TK in 2023.
- Updated versions of Burgundy's Engagement Plan were approved by the WLWB in 2023.

Assessment of Regulators

FISHERIES AND OCEANS CANADA

 Limited involvement in review & monitoring of fish/fish habitatrelated activities & in providing advice ENVIRONMENT AND CLIMATE CHANGE CANADA

 Generally provided valuable input and were active participants in reviews.
 Exception being Point Lake public hearing, were not able to respond to questions. WÈK'EEZHÌI LAND AND WATER BOARD

- Ensured timely reviews of reports and monitoring programs
- Well run public hearing for WL Renewal and technical session for Sable Underground

Assessment of Regulators

GNWT: Department of Environment and Climate Change (ECC)

Lands




- 2 WL and 9 LUP inspections over 7 site visits. Less than previous years
- Authorized 21.6 ha land covered by laydown pads; part of this extends into untouched watershed E of Sable Pit; no public review

Water Management and Monitoring



- 4 non-compliance events:
 - 2 discharges of non-compliant water from King Pond into Cujo Lake;
 - 2 discharges exceeding permitted volume.

Regulatory & Permitting Division: Enviro Impact Assessment Section





Assessment of Burgundy

- Agency has a positive relationship & open communications with Burgundy.
- Increased non-Compliance with water licence and permits.
- Progress in updating the ICRP is slower than we would expect; latest plan weak on details.
- General Site cleanliness needs attention.



AGENCY RECOMMENDATIONS TO BURGUNDY



MANAGEMENT OF COMPLIANCE ASSURANCE

up-to-date management systems & plans needed for consistent compliance with the WL and LUPs and effective implementation of operational environmental requirements.



CLOSURE & RECLAMATION

Old Camp:

- investigate causes of WQ exceedances in runoff;
- landform stability issues: develop better understanding of approaches that can be used for C&R activities at other sites.



Sable laydown pad extension

AGENCY RECOMMENDATIONS TO GNWT

GNWT ECC



 in conjunction with WLWB, should adjust requirements for liability estimates & security bond to account for closure costs for management of wastewater accumulated in pits used for storage of Fine PK.



 review its practices related to scope and scale of mining changes that inspectors can authorize under a Land Use Permit, including adoption of operational thresholds that would need a public review if exceeded.

Agency activities







EKATI-SPECIFIC HEARINGS & WORKSHOPS



SITE MODEL UTILIZED



DOCUMENT REVIEWS

